


May 3, 2006

Survivair has been informed by our cylinder supplier, Luxfer Gas Cylinders, that a small group of composite cylinders may not have been properly tested prior to shipping from their facility. These cylinders were shipped between May 1, 2005 through October 1, 2005. Survivair has been asked to assist them in locating these cylinders. Luxfer has supplied to Survivair a list of cylinder serial numbers that need to be returned to Luxfer for testing. See figure 1 for the location of the Luxfer serial number and manufacture date. Please compare your cylinders serial number to the list below. If you find that any of your cylinder serial numbers match the serial numbers in this list, contact Luxfer per the information contained on their attached notification document for further information and procedures.

Survivair 10 minute, 4500 psig fully wrapped carbon fiber cylinder. 917249 or 917250	Survivair 30 minute, 2216 psig fully wrapped carbon fiber cylinder. 917132, 917422, 917130, 917423, or 915188.
Luxfer part number L17D-6	Luxfer part number L45G-1
Serial Numbers: GO154 through GO165	Serial Numbers: IJ95899 through IJ95945

Survivair 30 minute, 4500 psig fully wrapped carbon fiber cylinder. 917404, 917133, 917405, 917131, or 915189.	Survivair 60 minute, 4500 psig fully wrapped carbon fiber cylinder. 917161, 917428, 917160, 917429, or 915192.
Luxfer part number L45J-1	Luxfer part number L65G-1
Serial Numbers: IO29576 through IO29670 and IO29812 through IO29867	Serial Numbers: IL201492, IL201503, IL201515, or IL201526

Figure 1



SURVIVAIR: 3001 South Susan Street – Santa Ana, CA 92704 USA Tel.: +1 888 APR-SCBA – Fax: +1 714 850-0299 – www.survivair.com





Notification to Owners and Users

February 21, 2006

Luxfer Gas Cylinders requests your help in locating a small group of Luxfer composite cylinders that may not have been properly autofrettaged and/or hydrostatically tested by a third-party inspector, Arrowhead Industrial Services, Inc. Records indicate that some of these cylinders may have been sold to you.

Luxfer has verified that the cylinders are safe based on thorough testing, detailed engineering analysis and data collected from many cylinders already recovered from the affected group. Every cylinder thus far tested has passed all required tests without incident. However, remaining cylinders must be recovered and tested as quickly as possible.

To determine whether you have cylinders that need to be tested, please compare serial numbers of your Luxfer cylinders that have hydrostatic test dates from May through September 2005 with serial numbers listed on the Luxfer website at www.luxfercylinders.com/ctest. (The sample label below shows where to find the serial number and hydrostatic test date.)

Once you have determined which cylinders, if any, need to be tested, please call this toll-free number: **1-800-355-3156**. A Luxfer customer-service representative will arrange to have your cylinders tested and returned to you at no charge.

We apologize for any inconvenience this may cause you. Please be assured that Luxfer will make every effort to get your cylinders back to you as quickly as possible.

Thank you for your understanding and assistance.

