

T E C H N I C A L B U L L E T I N

#79 February 16, 1993

DELETION OF DESIGNATED OVERHAUL REPLACEMENT PARTS LISTED IN THE 1993 PARTS BOOK; CARTRIDGE ALARM OVERHAUL

There are two items listed on page 15 of the 1993 Parts book that require clarification.

1. Item 50, the piston seat, P/N 911006, should have its designation as a standard overhaul part for the cartridge alarm deleted.
2. Item 19, the o-ring, P/N 957308, should also have its designation as a standard overhaul replacement deleted.

The cartridge alarm does not require periodic overhaul. Individual parts may be ordered as required for repair.