



# Air Cascade System Parts Assembly



- ① AC10014 CGA 347 Adapter
- ② AC50030 Check Valve
- ③ AC20021-1 Tee
- ④ AC10009 1/4 MPT x 1/4 JIC-F




- ① AC10014 CGA 347 Adapter
- ② AC50080 On/Off Line Valve
- ③ AC20021-1 Tee
- ④ AC20035 JIC x FPT Adapter
- ⑤ AC50030 Check Valve

1800-3000 PSI = CGA 346  
 3001-5500 PSI = CGA 347  
 5501-7500 PSI = CGA 702



PO Box 1000 Sophia WV, 304-683-4595 • 304-683-3257 Fax  
 www.americanairworks.com, All Rights Reserved. ©2006




- ① AC40040 4500 PSI DOT
- ② AC10031\* Nut & Nipple
- ③ AC80052 Pigtail, Flex, 24"
- ④ AC20023-1 JIC Tee
- ⑤ AC20161 JIC Cap

\*Compressor Connection

Optional AC50080 Line Valve

Add or delete cylinder banks with hardware as needed with these components.



- ① AC30019 6000 PSI Gauge
- ② AC30019 6000 PSI Gauge
- ③ AC60010 6000 PSI Inlet Pressure 50/5000 PSI Outlet Pressure
- ④ AC20013 1/4" MPT to 1/4" JIC-M Adapter

- AC20022-1 Street Tee From Cascade
- AC20010 Hex Nipple MPT Tee Connection
- AC10031 5500 PSI CGA 347 Nut & Nipple Single Cylinder
- AC10034 6000 PSI CGA 702 Nut & Nipple Single Cylinder

\*Change to AC10034 for 6000 PSI DOT Cylinders.